Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

Operator: AMEREN ILLINOIS COMPANY	Operator ID#: 32513
Inspection Date(s): 12/1/2015, 12/2/2015, 12/3/2015, 12/4/2015	Man Days: 4
Inspection Unit: Belleville/E. St. Louis	
Location of Audit: Belleville/O'Fallon	
Exit Meeting Contact: Chuck Tebbe	
Inspection Type: Design Testing and Construction	
Pipeline Safety Representative(s): Valerie Schwing	
Company Representative to Receive Report: Michael Fuller	
Company Representative's Email Address: mfuller2@ameren.com	
	·

CONSTRUCTION INFORMATION				
Location of Construction:	Construction Performed By:			
824 Bluff Ridge Lane, Belleville, IL	Ameren Illinois			
Contractor Foreman:				
Operator Inspector:				
Person(s) On Job Site				
Allen Hoernis	Zac Reis	Nate Capps		
Shaun Hattan	Ryan Veath			
Description of Construction:				

Ameren Illinois crew installed approximately 40 feet of 1/2 inch PE service line from a 2 inch PE main.

SERVICE INSTALLATION		Status
[192.55]	Steel	No
[192.59]	PE	Yes
[192.59]	Other	No
[192.619,192.621,192.623]	MAOP	60 PSI
[192.5]	Class location :	Class 1
[192.53]	Are components qualified for use?	Satisfactory
[192.63(a)(2)]	Pipe Size :	1/2" service

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

[192.55,192.59]	Specification :	ASTM 2513
[192.55,192.59]	Manufacturer :	DriscoPlex
[192.55,192.59]	Pipe Grade :	2406
[192.55,192.59]	Wall Thickness :	.09
[192.63]	Are pipe, valves, and fittings properly marked for identification?	Satisfactory
[192.227]	Welder qualification date:	Not Applicable
General Comment:		
Metallic pipe was not installed or exposed.		
[192.227]	Welder's Name:	Not Applicable
General Comment:		
Metallic pipe was not installed or exposed.		
[192.225,192.275,192.277,192.279,192.283	Is pipe joined in accordance with approved written procedures?	Satisfactory
General Comment:		
Staff observed the joiner making electrofusions in acco	rdance to the operator's POLY 2.05 procedures.	
[192.285]	Date of Qualification :	03/09/15
[192.285]	Joiner's name:	Zac Reis
[192.455]	Is buried metallic pipe coated?	Not Applicable
General Comment:		
Metallic pipe was not installed or exposed.		
[192.455(a)(1)]	Is cathodic protection being provided?	Not Applicable
General Comment:		
Metallic pipe was not installed or exposed.		
[192.455(a)(1)]	Is cathodic protection being provided? By Anodes:	No
[192.455(a)(1)]	Is cathodic protection being provided? By Rectifier:	No
[192.461]	Does coating meet 192.461?	Not Applicable
General Comment:		
Metallic pipe was not installed or exposed.		
[192.461(c)]	Is coating inspected just prior to being installed in the ditch?	Not Applicable
General Comment:	·	
Metallic pipe was not installed or exposed.		
[192.479]	Are above ground facilities cleaned and coated or jacketed as	Not Applicable

AMEREN ILLINOIS COMPANY/12-4-2015

Page 2 of 5

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

	needed?	
General Comment:		
Metallic pipe was not installed or exposed.		
[192.467]	Are pipelines electrically isolated from other underground metallic structures?	Not Applicable
General Comment:		
Metallic pipe was not installed or exposed.		
[192.319]	Is ditch back-filled to provide firm support and prevent damage to pipe or coating?	Satisfactory
General Comment:		
Staff observed the use of rock shield and san	d to provide firm support and prevent damage to the pipe.	
[192.321(c)]	Is plastic pipe installed as to minimize shear and tensile forces?	Satisfactory
General Comment:		
Staff observed the use of rock shield and san	d to provide firm support and prevent damage to the pipe.	
[192.321]	Does plastic pipe have means of locating while underground?	Satisfactory
General Comment:		
Staff observed the Ameren crew install a coal	ted tracer wire in accordance to the operator's POLY 1 procedures.	
[192.327(a)]	Is required cover being obtained for the service line?	Satisfactory
General Comment:		
Staff observed the Ameren crew install the 1/2	inch service line with a cover of 1 foot and 10 inches in accordance with the operator's SEF	RV 1 procedures.
[192.503]	Are general testing requirements being met?	Satisfactory
General Comment:		
Staff observed a pressure test of 100 PSI hel operator's PTST 2.01 procedures.	d for ten minutes in accordance with the operator's PTST 1 procedures and leak tested in a	ccordance with the
[192.517]	Are records being made of strength and leak tests?	Satisfactory
General Comment:		
Staff observed a pressure test of 100 PSI hel operator's PTST 2.01 procedures.	d for ten minutes in accordance with the operator's PTST 1 procedures and leak tested in a	ccordance with the
[192.807]	Were covered employees Operator Qualification records reviewed to ensure qualification?	Satisfactory
General Comment:		
Staff reviewed the qualifications of the joiner personnel were being directed.	and the journeyman Allen Hoernis to ensure the span of control limitations were followed an	d non-qualified
[192.805(c)]	Were non-qualified personnel being directed and observed by	Satisfactory

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.

followed and	l non-qualified
	Satisfactory
•	
followed and	l non-qualified
	No
	Satisfactory
). Staff obser	rved markings in
	X3220140
serving	Satisfactory
•	
	Satisfactory
•	

Unless otherwise noted, all code references are to 49CFR Part 192. If an item is marked Unsatisfactory, Not Applicable, or Not Checked, an explanation must be included in this report.